


Total Land Subsidence in the Ranegras Valley, La Paz County
 Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
 Time Period of Analysis: 2.0 Years 03/30/2016 To 03/20/2018

© MDA 2016 - 2018

Explanation

03/30/2016 To 03/20/2018

	Decorrelation/No Data		Subsidence Feature
	Greater 40 cm (15.7 in)		Hardrock
	25 - 40 cm (9.8 - 15.7 in)		CAP Canal
	15 - 25 cm (5.9 - 9.8 in)		Interstate
	10 - 15 cm (3.9 - 5.9 in)		US
	6 - 10 cm (2.4 - 3.9 in)		State
	4 - 6 cm (1.6 - 2.4 in)		Roads
	2 - 4 cm (0.8 - 1.6 in)		Railway
	1 - 2 cm (0.4 - 0.8 in)		
	0 - 1 cm (0 - 0.4 in)		



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 5/15/2018

